

In-service Corrosion Issues in Sustainment of Naval Aircraft



By: Rick Mendoza NAVAIR North Island Advanced Structures Design Group 28 August 2012



| a. REPORT unclassified | b. ABSTRACT unclassified | c. THIS PAGE unclassified | Same as Report (SAR) | 50 | | |
|---|--|--|---|--|--|--|
| 16. SECURITY CLASSIFIC | | 17. LIMITATION OF ABSTRACT | 18. NUMBER OF PAGES | 19a. NAME OF RESPONSIBLE PERSON | | |
| 15. SUBJECT TERMS | | | | | | |
| 14. ABSTRACT | | | | | | |
| | SETSDefense 2012: -30, 2012, San Diego | = | ainable Surface E | ngineering fo | or Aerospace and | |
| 12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited | | | | | | |
| 9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) | | | | 11. SPONSOR/MONITOR'S REPORT NUMBER(S) | | |
| | | | | 10. SPONSOR/MONITOR'S ACRONYM(S) | | |
| 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) NAVAIR, North Island Advanced Structures Design Group,San Diego,CA,92135 | | | | 8. PERFORMING ORGANIZATION REPORT NUMBER | | |
| | | | | 5f. WORK UNIT NUMBER | | |
| | | | | 5e. TASK NUMBER | | |
| In-service Corrosion Issues in Sustainment of Naval Aircraft 6. AUTHOR(S) | | | | 5d. PROJECT NUMBER | | |
| | | | | 5c. PROGRAM ELEMENT NUMBER | | |
| | | | | 5b. GRANT NUMBER | | |
| 28 AUG 2012 2. REPORT TYPE 4. TITLE AND SUBTITLE | | | | 00-00-2012 to 00-00-2012 5a. CONTRACT NUMBER | | |
| 1. REPORT DATE | | | | 3. DATES COVERED | | |
| maintaining the data needed, and c including suggestions for reducing | lection of information is estimated to completing and reviewing the collection this burden, to Washington Headquuld be aware that notwithstanding and DMB control number. | ion of information. Send comments arters Services, Directorate for Info | s regarding this burden estimate or formation Operations and Reports | or any other aspect of the s, 1215 Jefferson Davis | his collection of information, Highway, Suite 1204, Arlington | |

Report Documentation Page

Form Approved OMB No. 0704-0188



Synopsis

Corrosion Issues

- Dorsal Longeron Scallop corrosion.
- Inner Wing Corrosion.
- Outer Wing Corrosion.
- Fuel cell Floor Corrosion.
- Y395 Lug Corrosion.





Dorsal Longeron Doors






Dorsal Longeron
























INNER WING STRUCTURE







IWP DOOR SUBSTRUCTURE







DOOR 78/79/143/82 SUBSTRUCTURE





















IWP AFT SPAR/FOLD RIB INTERFACE


















































OUTER WING STRUCTURE







OWP DOOR 83/84 SUBSTRUCTURE








DOOR 84/84 SUBTRUCTURE









OWP AFT SPAR AILERON INBOARD & OUTBOARD HINGES














OWP FRONT SPAR


































NAVWAIR




































WING-FUSELAGE ATTACH BULKHEADS








WING-FUSELAGE ATTACH BULKHEADS





• Dissimilar Metals









GALVANIC SERIES OF METALS AND ALLOYS IN SEA WATER

ANODIC (High corrosion potential)


```
Magnesium Alloys
   Zink (plate)
     Beryllium
        Cadmium (plate)
          Uranium (depleted)
            Aluminum Alloys
                 Indium
                  Tin (plate)
                     Stainless Steel 430 (active)
                      Lead
                          1010 Steel
                            Cast Iron
                              Stainless Steel 410 (active)
                                  Copper (plate)
                                     Nickel (plate)
                                       AM 350 (active)
                                           Chromium (plate)
                                               Stainless Steels 350, 310, 301, 304 (active)
                                                Stainless Steels 430, 410 (passive)
                                                     Stainless Steel 13-8, 17-7 PH (active)
                                                       Brass, Yellow, Naval
                                                         Stainless Steel 316L (active)
                                                             Bronze 220
                                                               Copper 110
                                                             Stainless Steel 347 (active)
                                                            Copper-Nickel 715
                                                         Stainless Steel 202 (active)
                                                       Monel 400
                                                     Stainless Steel 202 (active)
                                                 Stainless Steels 321, 316 (active)
                                               Stainless Steels 309, 13-8, 17-7 PH (passive)
                                            Stainless Steels 304, 301, 321 (passive)
                                        Stainless Steels 201, 316L (passive)
                                     Stainless Steel 286 (active)
                                 AM355 (passive)
                               Titanium Alloys
                           Am350 (passive)
                      AM350 (passive)
                   Silver
               Palladium
             Gold
        Rhodium
    Platinum
Carbon/Graphite
```

CATHODIC (Low corrosion potential)





Y395 Inlet Nacelle Corrosion








CORROSION ON Y395





IMAGEWARE USE

- Manipulate points into curves
- Curves into surfaces.









Pro/MECHANICA

- Finite Element Analysis
- Durability Assessment











Current Analysis







Y395 Former Corrosion





EXCCESIVE CORROSION INSIDE CLEVIS


Y 395 Former





Y395 Corrosion Repair on Fuselage

Y395
 Prior to removal.







Y395 Corrosion Repair on Fuselage





Questions?

